

WOODHILL FIRE DEPARTMENT INCIDENT COMMANDER FACT SHEET

DATE OF INSPECTION: July 25, 1932

ADDRESS: Darvey Farm - East Overlook Road

CROSS STREET: None

DIRECTIONS: North on Court to East Overlook, turn right on East Overlook, continue east into Woodhill Township, first drive on left

1st ALARM: Woodhill Engines 1 and 2

2nd ALARM: Allan Falls Pumper and manpower Dalebridge Tanker, Ladder Truck and manpower

STAGING: Engine 2 stage at river for drafting Other apparatus stage on East Overlook

SPECIAL EQUIPMENT: Manpower, Tractor and blade on property (in parking lot), Tractor and plow from Hegerty farm if fire-break needed

OWNER AND OCCUPANCY INFORMATION

OWNER: Laura Darvey	TELEPHONE: EV-8280
OCCUPANT: Cottage Hill Farm	TELEPHONE: EV-1322
BUILDING SUPT: N/A	TELEPHONE:
BUILDING MGR: N/A	TELEPHONE:
ASST. MANAGER: N/A	TELEPHONE:

BUILDING NAME: Cottage Hill Farm  
BUILDING ADDRESS: East Overlook Road  
CONSTRUCTION TYPE: Wood frame  
PRINCIPAL OCCUPANCY: Horse Barn  
BUILDING DIMENSIONS: 35' x 80' 10 stalls 2-story  
FIRE WALL LOCATIONS: None  
ENTRY POINTS: Doors at each end of barn, door at middle of north side of barn  
PEOPLE IN BUILDING, DAY: Yes NIGHT: No, but HORSES in stalls  
POSSIBLE AREAS OF TRAPPED OCCUPANTS: Individual stalls  
DISABLED PERSONS NEEDING ASSISTANCE: None

WATER SUPPLY

HYDRANT/WATER SUPPLY LOCATIONS	STATUS	SIZE	FLOW
--------------------------------	--------	------	------

No hydrants, draft from river

WATER SUPPLY COMMENTS: River open year-round with good access on grass/gravel lane, kept open in winter

## CONSTRUCTION INFORMATION

ROOF TYPE: Gable roof  
ROOF CONSTRUCTION: Asphalt shingles  
FLOOR CONSTRUCTION: Concrete aisle, clay stalls  
BASEMENT TYPE: None

## UTILITIES INFORMATION

WATER: River, well  
GAS: None  
ELECTRIC: Fuse box in tack room, east end of barn  
INTERIOR ALARMS: None  
AIR CONDITIONING: None  
ELEVATOR: None  
HEATING: None

## PROTECTION METHODS

WATER SUPPLY: No, electric pump in barn with hose  
SPRINKLER SYSTEM: No  
STANDPIPE SYSTEM: No  
EXTERIOR ALARMS: Cast iron farm bell  
FIRE PUMP: No  
VENTILATION POINTS: Windows, doors  
FUEL LOAD: Very heavy load - hay on upper level  
F.D. CONNECTION: None  
SALVAGE OPERATIONS: Standard salvage operations  
SMOKE EVACUATION: Windows and doors

## ADDITIONAL COMMENTS

ANTICIPATED PROBLEMS: Horses in stalls, some young, need experienced horsemen to handle young horses and stallion. Hay storage on upper level above stalls is open to center aisle.

HAZARDS TO ADDITIONAL EXPOSURES: None

HAZARDS TO ENVIRONMENT: None

ADDITIONAL INFORMATION: Horses can be evacuated to any of the adjacent pastures.